

EDISON INTERNATIONAL  
Form 8-K  
October 21, 2004

=====

UNITED STATES  
SECURITIES AND EXCHANGE COMMISSION  
Washington, D.C. 20549

FORM 8-K

CURRENT REPORT

Pursuant to Section 13 or 15(d) of the Securities Exchange Act of 1934

Date of Report (Date of earliest event reported): October 21, 2004

EDISON INTERNATIONAL  
(Exact name of registrant as specified in its charter)

CALIFORNIA  
(State or other jurisdiction  
of incorporation)

001-9936  
(Commission  
File Number)

95-41  
(I.R.S.  
Identific

2244 Walnut Grove Avenue  
(P.O. Box 800)  
Rosemead, California 91770  
(Address of principal executive offices, including zip code)

626-302-2222  
(Registrant's telephone number, including area code)

=====

Check the appropriate box below if the Form 8-K filing is intended to simultaneously satisfy the obligation of the registrant under any of the following provisions:

- Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)
- Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)
- Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))
- Pre-commencement communications pursuant to Rule 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))

Page 1

*This current report includes forward-looking statements. These forward looking statements represent the registrant's current expectations and projections about future events based on knowledge of facts as of the date of this current report and assumptions about future events. These forward-looking statements are subject to*

## Edgar Filing: EDISON INTERNATIONAL - Form 8-K

*risks and uncertainties that may be outside the control of Edison International and its subsidiaries. Edison International has no obligation to publicly update or revise any forward-looking statements, whether as a result of new information, future events, or otherwise.*

### Section 8 - Other Events

#### Item 8.01 Other Events.

As previously disclosed, Southern California Edison Company's San Onofre nuclear plant has experienced degradation in its steam generator tubes, and the company is planning for replacement of the steam generator tubes in 2009 and 2010. The San Onofre units each include a pressurizer tank that contains 30 heater penetrations fabricated from the same material used in the steam generator tubes. These penetrations, also known as sleeves, are 13-inch long sections of pipe welded into the bottom of the pressurizer. During the current outage, Southern California Edison performed inspections of two sleeves and found evidence of degradation. Degradation of the pressurizer sleeves has been a concern in the nuclear industry for some time, and Southern California Edison had been planning to replace all of the sleeves in Units 2 and 3 during the next scheduled outage in 2005 and 2006. Southern California Edison has decided to move the planned replacement of the pressurizer sleeves forward from 2006 to the current outage. This extra work will lengthen the current outage from 55 days to the range of 95 to 110 days. Extending the current outage to do this work now allows Southern California Edison to move the 2006 refueling outage, previously scheduled for the summer of 2006, to the summer period to the fall or winter of 2006. Southern California Edison will incur about \$9 million in additional expenditures during 2005 that otherwise would have occurred in 2006. Southern California Edison will replace the pressurizer sleeves in Unit 2 during its next scheduled outage in 2005.

During the current outage, Southern California Edison also conducted a planned inspection of the reactor vessel head and found indications of degradation. Although the degradation is far below the level at which leakage would occur, Southern California Edison plans to make repairs during the current outage using readily available tooling and a Nuclear Regulatory Commission-approved repair technique. While this is Southern California Edison's first experience of this kind of degradation to the reactor vessel heads, the detection of similar degradation at other plants are now common in the industry. SCE plans to replace the Unit 2 reactor vessel heads during refueling outages in 2009-2010.

The California Public Utilities Commission will review the reasonableness of outage-related costs and replacement power costs in future ratemaking proceedings. Southern California Edison believes that the costs are reasonable, recovery of the costs should be authorized, and that the acceleration of the costs should not impact its earnings.

On October 21, 2004, Southern California Edison issued a press release announcing the planned replacement and repair activities. A copy of the press release is attached as Exhibit 99.1.

Page 2

### Section 9 - Financial Statements and Exhibits

#### Item 9.01 Financial Statements and Exhibits.

(c) Exhibits

See the Exhibit Index below.

### SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has caused this report to be signed on its behalf by the undersigned hereunto duly authorized.

EDISON INTERNATIONAL

Edgar Filing: EDISON INTERNATIONAL - Form 8-K

(Registrant)

/s/ KENNETH S. STEWART

-----  
KENNETH S. STEWART  
Assistant General Counsel and Assistant

DATE: OCTOBER 21, 2004

**EXHIBIT INDEX**

<b>Exhibit No.</b>	<b>Description</b>
99.1	Press Release of Southern California Edison Company of October 21, 2004.